



## URGENT MEDICAL DEVICE CORRECTION

### GE Healthcare

Healthcare Systems  
9900 Innovation Drive  
Wauwatosa, WI 53226  
USA

<Date of Letter Deployment>

GEHC Ref#32036

**To:** Manager Biomedical/Clinical Engineering  
Nurse Manager, Labor & Delivery/ NICU  
Manager, Respiratory Therapy/ Director of Risk Management

### **RE: Potential Safety Issue Involving GE Warmers with Nellcor SpO<sub>2</sub>**

GE Healthcare has recently become aware of a potential safety issue associated with the Nellcor SpO<sub>2</sub> alarm settings on the following GE Giraffe and Panda iRes Warmers:

- **Giraffe Warmers integrated with Nellcor SpO<sub>2</sub>**
- **Panda iRes Warmers integrated with Nellcor SpO<sub>2</sub>**
- **Panda Freestanding Warmers integrated with Nellcor SpO<sub>2</sub>**
- **Panda Wall-Mount Warmers integrated with Nellcor SpO<sub>2</sub>**
- **Nellcor SpO<sub>2</sub> Upgrade kit**

**Please ensure that all potential users in your facility are made aware of this safety notification and the recommended actions.**

#### **Safety Issue**

There may be a loss of internal communication that manages the user-adjusted Nellcor SpO<sub>2</sub> alarm settings of the affected Giraffe and Panda iRes Warmer systems with Nellcor SpO<sub>2</sub> listed above. If the issue exists, the alarms may not activate as expected, which can result in false positive or false negative saturation and pulse rate alarm notifications to the caregiver.

The patient's oxygen saturation and pulse rate values are accurate, as displayed; however, the displayed user-set alarm limits may be different than the actual alarm limits used for alarm activation. All other clinical functionality of the warmer is unaffected.

This alarm failure is caused by a software issue that does not detect a loss of internal communication that manages the user-adjusted Nellcor SpO<sub>2</sub> alarm settings.

#### **Safety Instructions**

You may continue to use your system provided you follow the GE recommended actions:

- 1) If in use with a patient, turn off the Nellcor SpO<sub>2</sub> function in the control panel and switch to an approved alternate form of SpO<sub>2</sub> measurement.
- 2) Prior to using the affected GE warmer with the Nellcor SpO<sub>2</sub> function, or resuming the use of this function with any patient, contact your hospital Bio-Med or qualified technician to check the Nellcor SpO<sub>2</sub> alarm functionality using either an adult Nellcor SpO<sub>2</sub> sensor or a Nellcor SpO<sub>2</sub> simulator following the applicable instructions in the Appendix (see pages 3-4).
- 3) If the test activates a 'Low Pulse Rate' alarm, the user-adjusted Nellcor SpO<sub>2</sub> alarm limits are functioning properly and the warmer can be placed back in clinical service.

PLEASE NOTE: Alarm functionality must be re-checked following every service event requiring access to the internal electronics and during annual preventative maintenance, until revised software is installed.

4) If the test does NOT activate a 'Low Pulse Rate' alarm, remove the warmer from clinical service and contact your local GE Healthcare Service Representative.

**Affected  
Product  
Details**

All Giraffe Warmers integrated with Nellcor SpO<sub>2</sub>  
Panda iRes Warmers integrated with Nellcor SpO<sub>2</sub>  
Panda Freestanding Warmers integrated with Nellcor SpO<sub>2</sub>  
Panda Wall-Mount Warmers integrated with Nellcor SpO<sub>2</sub>  
Nellcor SpO<sub>2</sub> Upgrade kit

**Product  
Correction**

GE Healthcare will correct all affected systems with a software revision at no cost to you. A GE Healthcare service representative will contact you to arrange for this correction.

**Contact  
Information**

If you have any questions or concerns regarding this notification, please call the following phone numbers:

Saudi Arabia Toll Free number: 8004292222

Saudi Arabia Service Center: SaudiArabiaServiceCenter@ge.com

You can also contact your local GE Healthcare Service Representative.

Please be assured that maintaining a high level of safety and quality is our highest priority. If you have any questions, please contact us immediately per the contact information above.

Sincerely,



James Dennison  
Vice President QARA  
GE Healthcare Systems



Douglas M. Hansell, M.D., MPH  
Chief Medical Officer  
GE Healthcare

## Appendix

### A. Testing Nellcor SpO<sub>2</sub> Alarm Functionality Using SpO<sub>2</sub> Simulator

To confirm that the warmer with Nellcor SpO<sub>2</sub> is activating the alarms based on the user-set limits, ensure patient is removed, and then generate a 'Low Pulse Rate' alarm by completing the following steps:

1. Connect SpO<sub>2</sub> simulator to the Nellcor probe jack shown below.



2. Turn On the SpO<sub>2</sub> feature by pressing the key to the left of the SpO<sub>2</sub> box.



3. Access the SpO<sub>2</sub> Alarm Limit settings by first pressing "Menu" key on the right of the screen and then the "SpO<sub>2</sub>" key. Next, press the "Alarm Limits" key (shown below) to change the alarm limit settings for pulse rate or SpO<sub>2</sub>.



4. Set the 'Low Pulse Rate' limit to 110.
5. Using the SpO<sub>2</sub> Simulator, simulate a pulse rate greater than 40 and lower than 110.
6. Confirm a "Low Pulse Rate" alarm activates.

## Appendix

### B. Testing Nellcor SpO<sub>2</sub> Alarm Functionality Using an Adult Nellcor SpO<sub>2</sub> Sensor

To confirm that the warmer with Nellcor SpO<sub>2</sub> is activating the alarms based on the user-set limits, ensure patient is removed, and then generate a 'Low Pulse Rate' alarm by completing the following steps:

1. Position the adult SpO<sub>2</sub> sensor on the adult finger.
2. Next, connect the sensor to the patient cable.
3. Plug the patient cable into the Nellcor probe jack shown below.



4. Turn On the SpO<sub>2</sub> feature by pressing the button to the left of the SpO<sub>2</sub> box.



5. Access the SpO<sub>2</sub> Alarm Limit settings by first pressing "Menu" key on the right of the screen and then the "SpO<sub>2</sub>" key. Next, press the "Alarm Limits" key (shown below) to change the alarm limit settings for pulse rate or SpO<sub>2</sub>.



6. Set the Low Pulse Rate limit to 110.
7. Measure the pulse rate. The measured pulse rate must be greater than 40 and less than 110, if it is not please use a SpO<sub>2</sub> simulator to test the system.
8. Confirm a **Low Pulse Rate** alarm activates.