

Value Segment Solution

-1/4-

FSN86000263A,264A

2018 Dec

URGENT - Medical Device Correction Philips PageWriter TC Cardiographs (TC20/30/50/70) User Maintenance of Lithium Ion Batteries

Dear Customer,

A problem has been detected with the Philips PageWriter TC Cardiographs (TC20/30/50/70), that, if it were to re-occur, could pose a risk for patients or users. This Field Safety Notice is intended to inform you about:

- what the problem is and under what circumstances it can occur
- the actions that should be taken by the customer / user in order to prevent risks for patients or users
- the actions planned by Philips to correct the problem.

This document contains important information for the continued safe and proper use of your equipment

Please review the following information with all members of your staff who need to be aware of the contents of this communication. It is important to understand the implications of this communication.

Please retain a copy with the equipment Instruction for Use.

Philips has received a report in which the lithium ion battery in a PageWriter TC Cardiograph overheated and ignited. The battery had exceeded its life expectancy and should have been replaced. Battery replacement should have occurred when the number of charge-discharge cycles first exceeded 300 cycles or when the battery capacity fell below 80% of that of a new battery. Although the cardiograph can display the battery's status, the existing labeling for these cardiographs does not include full instructions on when to replace the batteries or the potential hazards if a user fails to do so. Therefore, Philips is issuing a PageWriter TC Cardiograph (TC20/30/50/70) Service Manual addendum with information to assist users with managing the battery and its replacement. The Service Manual Addendum is included with this letter.

Please refer to the following pages, which provide information on how to identify affected devices and instructions for actions to be taken. Follow the "Action to be taken by Customer/User" section of the notice. This notice has been reported to the appropriate Regulatory Agency.

Philips sincerely regrets the inconvenience that this may cause you. Your satisfaction with Philips' products and with our response to this issue is very important to us. Please contact Philips representative contact details to be completed by the KM / country> with questions or concerns about this correction.

Sincerely,

Vivian Dai Post Market Surveillance Manager

AFFECTED PRODUCTS	manufactured be battery power and Specifically, the fup to and including Product 860315 860310 860332 860352 860353 860354 860355 860429	ducts are all PageWriter TC Cardiographs (TC20/30/50/70) If ore November 20, 2018 that are capable of operating under d have lithium-ion batteries presently installed. Following PageWriter TC Cardiographs with software revisions and A.07.05.22. Description PageWriter TC70 PageWriter TC50 PageWriter TC30 PageWriter TC70 PageWriter TC70 w/trolley Government Bundle PageWriter TC70 w/trolley Government Bundle PageWriter TC30 w/trolley Government Bundle PageWriter TC30 w/trolley Government Bundle PageWriter TC30 w/o trolley Government Bundle PageWriter TC30 w/o trolley Government Bundle PageWriter TC50 Government Bundle PageWriter TC50 Government Bundle		
PROBLEM DESCRIPTION	Philips has received a report in which the lithium ion battery in a Philips PageWriter TC cardiograph overheated and ignited. In this case, the battery had exceeded its life expectancy and should have been replaced when the number of charge-discharge cycles first exceeded 300 cycles or when the remaining battery capacity fell below 80% of that of a new battery. Although the Philips PageWriter TC Cardiographs can display actual information on the battery State of Health (SOH) and charge-discharge cycles, the existing labeling does not include full instructions on how to use this information to determine when to replace the battery.			
HAZARD INVOLVED	Overheating of the battery may cause the device exterior case to become excessively hot, causing the case to melt and/or the device to ignite, which can cause injury to a patient, nearby users, or cause damage to property.			

HOW TO IDENTIFY AFFECTED PRODUCTS

You can determine whether your device is affected by identifying the software revision. This can be performed by;

- a) Locate and verify the Product Number of your PageWriter TC cardiograph found on the cover page of the *Instructions for Use* or on the back label of your cardiograph, and
- b) Locate and verify the software revision on the PageWriter TC cardiograph's *System Utility* screen.

To determine if your device is capable of battery operation, verify on the upper right hand corner of the cardiograph's display to see if the battery symbol is exhibited.



ACTION TO BE TAKEN BY CUSTOMER / USER

Upon receipt of this notification, carefully read the enclosed PageWriter TC Service Manual Addendum.

Promptly determine the number of cycles and the State of Health (SOH) on each of your affected Philips PageWriter TC cardiographs (TC20/30/50/70), as specified in the attached *Service Manual Addendum*.

If the number of cycles is greater than 300 and/or if the SOH is less than 80%, this indicates that your battery has reached the end of its life and requires replacement. An approved replacement battery can be ordered using the standard Philips replacement processes. Details on how to replace the battery can be found in the PageWriter TC Cardiograph Service Manual Addendum.

Once it is determined the battery is not in need of replacement, or once the battery is replaced, the PageWriter TC Cardiograph is safe to continuing using.

In addition, review this information with all staff members who are responsible for device management of the Philips PageWriter TC cardiographs.

Please store the below *Service Manual Addendum* with your Philips PageWriter TC cardiograph Service Manual documentation.

Complete and return the response card provided.

ACTIONS PLANNED BY PHILIPS

Philips plans to release a customer installable, software update for PageWriter TC cardiograph (TC20/30/50/70) that will provide alerts to assist users in managing the battery replacement cycle. You will be notified when the customer installable software update is available.

FURTHER INFORMATION AND SUPPORT

If you need any further information or support concerning this issue, please contact your local Philips representative:

<Philips representative contact details to be completed by the KM / country>

Field Safety Notice Philips Healthcare



Value Segment Solutions

Dec 2018

FSN86000263A

URGENT - Medical Device Correction PageWriter TC Cardiographs (TC20/30/50/70)

Customer Reply for FSN86000263A PageWriter TC Cardiographs (TC20/30/50/70) Service Manual Addendum

Please complete and fax to < Philips representative contact details to be completed by the KM/country>.

Contact Name				
Telephone Number				
Email Address				
Facility Name				
Street Address				
City, State, Zip				
Please fax or email tl	nis completed form	to the number	or email address provided	above.
CUSTOMER ACKNO	WLEDGEMENT:	:		
That the PageWriter TC attached to the first page and is stored with the Se	e of the <i>Maintaining</i>	g the Battery sec	rvice Manual Addendum has tion to ensure that it is not m	been isplaced
Confirm all PageWriter than 300 cycles and/or t replacement batteries as	TC Cardiographs (7) he State of Health (8) called out in the Se	ΓC20/30/50/70) SOH) is ≤ 80 % ervice Manual A	batteries with cycle count gr have been replaced with app ddendum.	eater proved
CUSTOMER NAME (plea	se print)		TITLE	
CUSTOMER SIGNATUR	 E		DATE	
Dl	4 - 1 1 C 4 T	51.11		

Please email the completed reply form to Philips representative contact details to be completed by the KM/country>.. If you experience difficulty carrying out the instructions contained in this communication, contact your local Philips representative.