

URGENT MEDICAL DEVICE CORRECTION

GE Healthcare 3000 N. Grandview Blvd. - W440 Waukesha, WI 53188, USA

<Date of Letter Deployment>

GEHC Ref# FMI 34087

To: Director of Respiratory Chief of Anesthesia Director of Biomedical / Clinical Engineering Health Care Administrator / Risk Manager

RE: CARESCAPE R860 ventilator – Potential for the display processor to experience an unexpected failure.

Please ensure that all potential users in your facility are made aware of this safety notification and the recommended actions.

Safety Issue	There is a potential for the display processor to experience an unexpected failure. If this failure occurs, the device screen will temporarily go blank and will then display an Error Code "EC01 XX". The blank display results in loss of monitored data being displayed to the user. There have been no injuries reported as a result of this issue.
Safety Instructions	You may continue to use the system. Device performance is not affected on devices where no such display failure occurs.
	In the event this issue occurs, an audible alarm will sound. Mechanical ventilation will continue at previous settings. A device restart is required to clear the alarm condition. Consider using appropriate alternative means of ventilation such as a self-inflating bag or another ventilator to prevent patient injury while restarting the device.
Affected Product	CARESCAPE R860 ventilators with software version 10SP05
Details	GTIN # 00840682102346
Product Correction	GE Healthcare will correct all affected products at no cost to you. A GE Healthcare representative will contact you to arrange for the correction.
Contact Information	If you have any questions or concerns regarding this notification, please contact GE Healthcare Service at Toll Free number (Inside Saudi Arabia Only): LCS: 8004292222 or <u>J</u> SaudiArabiaServiceCenter@ge.com or your local Service Representative.

Please be assured that maintaining a high level of safety and quality is our highest priority. If you have any questions, please contact us immediately per the contact information above.